

# Фрезы для обработки ТИТАНОВЫХ СПЛАВОВ

Цилиндрический хвостовик и перекрытый центр






Схема	Обозначение	D	l	L	d	z
	T 534-4-11-43-C4	4	11	43	4	3
	T 534-4-19-51-C4	4	19	51	4	3
	T 534-5-13-47-C5	5	13	47	5	3
	T 534-5-24-58-C5	5	24	58	5	3
	T 534-6-16-52-C6	6	16	52	6	3
	T 534-6-30-66-C6	6	30	66	6	3
	T 534-8-19-59-C8	8	19	59	8	3
	T 534-8-38-78-C8	8	38	78	8	3
	T 534-10-22-72-C10	10	22	72	10	3
	T 534-10-45-95-C10	10	45	95	10	3
	T 534-12-26-81-C12	12	26	81	12	3
	T 534-12-53-108-C12	12	53	108	12	3
Группа применения						
P	M	K	N	S	H	
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
ТУ 25.73.40-049-36293294-2019						